

Technical change to HDC HB6 SDVL 2xM25 SET

Dear Madam or Sir,

the below listed articles will be supplied in a modified revision. Please pass this product information on to your employees and, if needed, to your customers. All modifications are performed for reasons of product improvements.

1. Initial situation

The HDC HB6 SDVL 2xM25 SET connector set consists of various components, including the cable gland 1778350000 VGM25-MS54 KB 15.0-17.0

2. Technical change

The included cable gland 1778350000 VGM25-MS54 KB 15.0-17.0 will be replaced with the 1909920000 VG M25-1/MS68 cable gland for every new production with immediate effect.



3. Reason for change

The cable gland 1778350000 VGM25-MS54 KB 15,0-17,0 will be cancelled soon.

4. Availability

The change applies to all newly produced sets.

Existing stock is not adjusted.

The change has no influence on the delivery performance or function of the product.

5. Affected parts

- 1822000000 HDC HB10 SVU 2xM25 SET
- 1822010000 HDC HB16 SVU 2xM25 SET
- 1822020000 HDC HB16 SDVL 2xM25 SET
- 1822120000 HDC HB6 SDVL 2xM25 SET
- 1822170000 HDC HA10 SDVL 2xM25 SET

6. Data

PCN-number: PCN-PKDPB72-20180329-00-A

Date of publishing: March 29th, 2018

Duration of validity: no time limit, until products will be cancelled

Revision number: 00

We are very sorry for all the inconveniences caused and doing everything to adjust this product change as smooth as possible without big influence on delivery times and general functions.

For further questions please contact your sales office directly. All contacts for sales representatives are available here: www.weidmueller.com/contact

Best regards

Product Management

Weidmüller Interface GmbH & Co. KG
Klingenbergstraße 16, 32758 Detmold, Germany

Weidmüller – Your partner in Industrial Connectivity
We look forward to sharing ideas with you – **Let's connect.**