

## Technical change to OMNIMATE Signal PCB terminals LL2N 5.0x – Standardization of Housing


Dear Madam or Sir,

the below listed articles will be supplied in a modified revision. Please pass this product information on to your employees and, if needed, to your customers. All modifications are performed for reasons of product improvements.

### 1. Technical change

**We have adjusted the housing of LL2N 5.0x, detailed change is as below**

- position of silk screen like insulation material and company logo moves
- structure above the exposed metal part has been optimized



### 2. Reason for change

As continuous standardization on product is a strategy to keep product competency in the market, we have been optimizing OMNIMATE Signal LL2N 5.0x/90 to achieve such goal.

### 3. Availability

The production of the new version will start in the beginning of 2019. Afterwards the stock change is an ongoing process. Parts with previous design will still be delivered continuously until the inventory is used up.

### 4. Affected parts

Material	Material Description
1324390000	LL2N 5.08/04/90 3.2SN BK BX
1469620000	LL2N 5.08/08/90 3.2SN BK BX
1922900000	LL2N 5.00/04/90 4.5SN ABGR
1934290000	LL2N 5.08/04/90 3.2SN OR BX
1934310000	LL2N 5.00/04/90 3.2SN OR BX
1977260000	LL2N 5.00/08/90 3.2SN OR BX
1977280000	LL2N 5.00/12/90 3.2SN OR BX
1977310000	LL2N 5.00/16/90 3.2SN OR BX
1977330000	LL2N 5.00/20/90 3.2SN OR BX
1977350000	LL2N 5.00/24/90 3.2SN OR BX
1977370000	LL2N 5.00/28/90 3.2SN OR BX
1977390000	LL2N 5.00/32/90 3.2SN OR BX
1977410000	LL2N 5.00/36/90 3.2SN OR BX
1977450000	LL2N 5.00/44/90 3.2SN OR BX
1977470000	LL2N 5.00/48/90 3.2SN OR BX
1977480000	LL2N 5.08/08/90 3.2SN OR BX
1977500000	LL2N 5.08/12/90 3.2SN OR BX
1977520000	LL2N 5.08/16/90 3.2SN OR BX
1977540000	LL2N 5.08/20/90 3.2SN OR BX
1977560000	LL2N 5.08/24/90 3.2SN OR BX
1977580000	LL2N 5.08/28/90 3.2SN OR BX
1977600000	LL2N 5.08/32/90 3.2SN OR BX
1977620000	LL2N 5.08/36/90 3.2SN OR BX
1977640000	LL2N 5.08/40/90 3.2SN OR BX
1977660000	LL2N 5.08/44/90 3.2SN OR BX
1977680000	LL2N 5.08/48/90 3.2SN OR BX
2469440000	LL2N 5.08/04/90 3.2SN GN BX

We are very sorry for all the inconveniences caused and doing everything to adjust this product change as smooth as possible without big influence on delivery times and general functions.

For further questions please contact your sales office directly. All contacts for sales representatives are available here: [www.weidmueller.com/contact](http://www.weidmueller.com/contact)

Best regards

Product Management

Weidmüller Interface GmbH & Co. KG  
Klingenbergstraße 16, 32758 Detmold, Germany

**Weidmüller** – Your partner in Industrial Connectivity  
We look forward to sharing ideas with you – **Let's connect.**